

# Oil Field Environmental Incident Summary

**Incident:** 20150122175345      **Date/Time of Notice:** 01/22/2015 17:53

**Responsible Party:** Missouri Basin Well Service Inc

**Well Operator:** MISSOURI BASIN WELL SERVICE, INC.

**Well Name:** HYSTAD SWD 1

**Field Name:** POE

**Well File #:** 8977

**Date Incident:** 1/22/2015

**Time Incident:** 11:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 151

**Rng:** 100

**Sec:** 2

**Qtr:** SW SE

**Location Description:**

**Submitted By:** Joshua Staggs

**Received By:**

**Contact Person:** Dave Wanner  
PO BOX 458  
BELFIELD, ND 58622

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other - List Under Desc of Cause below

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	62	Gallons	30	Gallons	62	gallons
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 2/10/2015

**Clean Up Concluded:** 2/4/2015

**Risk Evaluation:**

None, spill is contained on site.

**Areal Extent:**

***Potential Environmental Impacts:***

None, spill is contained on site.

***Action Taken or Planned:***

Spill was contained using items from spill kit(dry absorb, sand bags, weirs, etc.). The company is undergoing a thorough investigation to ensure all trucks are using metal hose valve caps as opposed to plastic.

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 1/23/2015    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to some type of treater upset, remained on location according to the report. NDIC retains oversight.